


# INSTRUCTION SHEET




**KEPCO** An ISO 9001 Company.

**MA  
RKW/GE  
35H**

## MOUNTING ADAPTER MA RKW/GE 35H

**DESCRIPTION.** The RoHS-compliant Model MA RKW/GE 35H Mounting Adapter includes an adapter plate, spacers and mounting screws that allow a 35W GE power supply to be easily substituted for a horizontally-mounted 30W RKW power supply. Mount the adapter plate to the GE power supply using the screws and spacers provided at mounting holes A (see Figure 1), then install the adapter plate in place of the RKW power supply using two 4-40 screws (not supplied) at mounting holes B on the adapter plate. NOTE: Max. penetration of 4-40 screws at holes B must not exceed 1/4 inch.



### NOTES:

1. MOUNT ADAPTER PLATE TO POWER SUPPLY USING TWO SCREWS AND TWO SPACERS (SUPPLIED) AT "A" HOLES AS SHOWN.
2. INSTALL ADAPTER PLATE WITH POWER SUPPLY ATTACHED USING TWO 4-40 SCREWS (NOT SUPPLIED) AT "B" HOLES.
3. MAX PENETRATION OF 4-40 SCREWS AT "B" HOLES MUST NOT EXCEED 1/4 INCH.

3043846

**FIGURE 1. ADAPTER PLATE INSTALLATION**

KEPCO, INC. ● 131-38 SANFORD AVENUE ● FLUSHING, NY. 11355 U.S.A. ● TEL (718) 461-7000 ● FAX (718) 767-1102  
<http://www.kepcopower.com> ● email: [hq@kepcopower.com](mailto:hq@kepcopower.com)