


INSTRUCTION SHEET



KEPCO An ISO 9001 Company.


**MA
RAX/RTW
-150H**

MOUNTING ADAPTER MA RAX/RTW-150H

DESCRIPTION. The Model MA RAX/RTW-150H Mounting Adapter includes an adapter plate and mounting screws that allow a 150W RTW power supply to be easily substituted for a horizontally-mounted 175W RAX power supply. Mount the adapter plate to the RTW power supply using the screws provided (see Figure 1), then install the adapter plate in place of the RAX power supply using the screws that previously secured the RAX power supply.

NOTES:

1. MOUNT ADAPTER PLATE TO RTW POWER SUPPLY AT HOLES "A" USING TWO SCREWS PROVIDED.
2. INSTALL ADAPTER PLATE WITH RTW POWER SUPPLY ATTACHED USING HARDWARE (NOT SUPPLIED) PREVIOUSLY USED TO MOUNT RAX POWER SUPPLY, EITHER AT HOLES "B" OR AT HOLES "C." IF HOLES "C" ARE USED, ENSURE MAX PENETRATION OF SCREWS DOES NOT EXCEED 0.24 IN. (6MM).



3044240

FIGURE 1. ADAPTER PLATE INSTALLATION

KEPCO, INC. ● 131-38 SANFORD AVENUE ● FLUSHING, NY. 11355 U.S.A. ● TEL (718) 461-7000 ● FAX (718) 767-1102
<http://www.kepcopower.com> ● email: hq@kepcopower.com