## INSTRUCTION SHEET



KEPCO An ISO 9001 Company.


MA HWS/AK -350/450V

## MOUNTING ADAPTER HWS/AK-350V, HWS/AK-450V

**DESCRIPTION.** The Model MA HWS/AK-350V is for 350W AK power supplies and Model MA HWS/AK-450V is for 450W AK power supplies. Each Mounting Adapter includes an adapter plate, spacers and mounting screws that allow a vertically-mounted 350W or 450W AK power supply to be easily substituted for a vertically-mounted 300W HWS power supply. Note that some AK dimensions may exceed corresponding HWS dimensions; verify proper fit prior to installation. Mount the adapter plate to the AK power supply using the screws and spacers provided (see Figure 1), then install the adapter plate in place of the HWS power supply using the screws previously used to mount the HWS power supply.

## NOTES:

- MOUNT ADAPTER PLATE TO POWER SUPPLY AT HOLES "A" USING FOUR SPACERS P/N 104-0312, AND FOUR SCREWS P/N 101-0487.
- 2. REMOVE HWS POWER SUPPLY AND SAVE MOUNTING SCREWS, THEN INSTALL ADAPTER PLATE WITH AK POWER SUPPLY ATTACHED AT HOLES "B." USING MOUNTING SCREWS SAVED. (MOUNTING SCREWS ARE M4, LENGTH NOT TO EXCEED 8MM.)






FIGURE 1. ADAPTER PLATE INSTALLATION

KEPCO, INC. ● 131-38 SANFORD AVENUE ● FLUSHING, NY. 11355 U.S.A. ● TEL (718) 461-7000 ● FAX (718) 767-1102 http://www.kepcopower.com ● email: hq@kepcopower.com

3044023