


INSTRUCTION SHEET



KEPCO An ISO 9001 Company.

**MA
RKW/AK
-650H**

MOUNTING ADAPTER RKW/AK-650H

DESCRIPTION. The Model MA RKW/AK-650H Mounting Adapter includes an adapter plate and mounting screws that allow a horizontally-mounted 650W AK power supply to be easily substituted for a horizontally-mounted 300W or 600W RKW power supply. Mount the adapter plate to the AK power supply using the screws and spacers provided (see Figure 1), then install the adapter plate in place of the RKW power supply using the screws previously used to mount the RKW power supply.

NOTES:

1. MOUNT ADAPTER PLATE TO POWER SUPPLY AT HOLES "A" USING THREE SPACERS P/N 104-0312, AND THREE SCREWS P/N 101-0476.
2. REMOVE RKW POWER SUPPLY AND SAVE MOUNTING SCREWS, THEN INSTALL ADAPTER PLATE WITH AK POWER SUPPLY ATTACHED AT HOLES "B." FOR RKW 600W AND HOLES "C." FOR RKW 300W, USING MOUNTING SCREWS SAVED.(MOUNTING SCREWS ARE M4, LENGTH NOT TO EXCEED 8MM).




FIGURE 1. ADAPTER PLATE INSTALLATION

KEPCO, INC. ● 131-38 SANFORD AVENUE ● FLUSHING, NY. 11355 U.S.A. ● TEL (718) 461-7000 ● FAX (718) 767-1102
www.kepcopower.com ● email: hq@kepcopower.com