


INSTRUCTION SHEET



KEPCO An ISO 9001 Company.

RA 15-1

RA 15-1 RACK ADAPTER

I — DESCRIPTION.

This kit contains the hardware required to mount one PRM Size B-120 Series Power Supply to a standard 19-inch equipment rack.

II — EQUIPMENT SUPPLIED

Table 1 lists the equipment supplied.

TABLE 1. EQUIPMENT SUPPLIED

Item	Quantity	Description	Kepco P/N
Panel	1	Allows installation of Series B-120 PRM power supply on standard 19-inch rack.	131-0468
Handle	2	Facilitates moving and installing rack adapter.	139-0095
Screw	4	Used to attach handle to panel (8-32 x 1/2, ST. FLS2).	101-0027
Screw	5	Used to attach PRM power supply to panel (8-32 x 1/2, ST., THPH).	101-0029
Washer	5	Used to attach PRM power supply to panel (#8, rolled, Nylon).	103-0068

III — ASSEMBLY

Attach the handle to the panel using four screws (P/N 101-0027) at mounting holes C (see Figure 1), Remove existing screws from PRM mounting holes as needed, then attach the PRM power supply to the panel using five screws (P/N 101-0029) and washers (P/N 103-0068) at mounting holes A.

IV — INSTALLATION

Mount the assembled rack adapter with the PRM power supply attached to the 19-inch rack using hardware (not supplied) at mounting holes B.




FIGURE 1. RACK ADAPTER RA 15-1